


Mila Elementary School - Site Drainage



The roof downspouts drain to the courtyard which does not have a drainage outfall system. This results in flooding the courtyard and areas around the courtyard.

Mila Elementary School - Classroom Doors



This is an example of a door that will be removed. The space will be filled and painted.



Mila Elementary School – Classroom Ceilings



This is an example of a truncated ceiling that will be removed due to the HVAC work above the ceiling. The ceiling will be replaced with a new grid and new tiles. Lighting will be converted to LED. This scope of work is planned for all classrooms except Building 9.

Mila Elementary - Classroom Floors



Distressed flooring will be replaced as resources allow.